


# 2023 Stormwater Infrastructure Inventory

Chester Borough  
Morris County  
New Jersey



**Legend**

**Inlet Condition**

- ★ Good
- Bad Structure
- Bad Debris
- ▲ Poor Both

**Outfall Condition**

- ◆ Good
- ◇ Fair
- ◇ Poor

**Other Stormwater Features**

- Manholes
- ← Pipe Flow Direction

**Roads**

- ▬ Primary Limited Access or Interstate
- ▬ Primary US and State Highways
- ▬ Secondary State and County Highway
- ▬ Local or Rural Road

**Boundaries**

- ▬ Chester Borough
- ▬ Other Municipalities

Coordinate System: NAD 1983 State Plane  
New Jersey FIPS 2900 Feet  
Projection: Transverse Mercator  
Datum: North America 1983  
Units: US Feet  
Date: May 2023

1 inch = 400 feet



**Disclaimer:**  
Pipe flow direction was determined by visual observation.  
Pipe inverts were not used in the flow direction determination.

PREPARED BY:  
**STORMWATER**  
COMPLIANCE SOLUTIONS, LLC